


1103-04 HINGE TEMPLATE

MODEL 1114, 1116, 1118 & 1120 CONCEALED ELECTRIC THROUGH WIRE & MONITOR & CONCEALED AIR TRANSFER

FOR USE WITH ALL MANUFACTURERS

5.0" FULL MORTISE 3 KNUCKLE BALL BEARING

HINGES STANDARD AND HEAVY WEIGHT



HINGES ARE NON-LOAD BEARING
AND MUST BE MOUNTED
IN THE CENTER POSITION ONLY.